

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0551 Pearson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	6.78	10/14/2015 10/14/2015	Herman Phillips

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0551_01_s _ 2012_3				
Action/Comments					
Inspector Comments: District has emergency supplies stored in locked container near Courtland's fire house.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0551_01_s _ 2012_15				
Action/Comments					
Inspector Comments: District has been trained in Flood Fight Methods					

No Photos

LM Start		Rating **	A	Issue No.	23
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0551_01_s _ 2012_23				
Action/Comments					
Inspector Comments: District has O&M Manual on hand and stored with flood fight materials.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0551 Pearson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	6.78	10/14/2015 10/14/2015	Herman Phillips

LM Start	0.00	Rating **	A	Issue No.	27
LM End	6.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.336439 °	38.258886 °
				-121.564765 °	-121.517901 °
DWR ID	DWR_RD0551_01_f_2015_27				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: All unwanted has been removed from the levee section.					

Photo 1 of 1 : FA_2015_RD0551_175_27_20151019_00018.jpg



Looking downstream from levee mile 0.00 to levee mile 6.78 all unwanted grasses has been removed from both the landside and waterside levee slopes.

LM Start	0.03	Rating **	M	Issue No.	25
LM End	0.03	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.336123 °	38.336123 °
				-121.565022 °	-121.565022 °
DWR ID	DWR_RD0551_01_f_2015_25				
Action/Comments					
Garbage Inspector Comments: Remove the garbage and mattress from the waterside slope.					

Photo 1 of 2 : FA_2015_RD0551_175_25_20151019_00016.jpg



RD 551 looking downstream from levee mile 0.02 garbage dumped on the waterside slope.

LM Start	0.03	Rating **	M	Issue No.	25 (cont)
LM End	0.03	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD0551_175_25_20151019_00017.jpg



Discarded mattress dumped on the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0551 Pearson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	6.78	10/14/2015 10/14/2015	Herman Phillips

LM Start	0.42	Rating **	M	Issue No.	19
LM End	0.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.331962 °	38.331962 °
				-121.569890 °	-121.569890 °
DWR ID	DWR_RD0551_01_f _ 2014_19				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---